



PILOT BOARDING DEFICIENCY REPORT

DATE: 04/10/19 TIME: 1230VESSEL: STI LEBLON V7VAG

MASTER: _____

PILOT: G. SMITHCONDITIONS: CLEAR / DRY

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
☐ COMBINATION LADDER
☐ SIDE PORT
☒ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☒ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

LADDER SUPPORTED ON PALLETSBERTH KM1 #3

Signature: _____

MASTER (if available)

G. SMITH
PILOT

