



PILOT BOARDING DEFICIENCY REPORT

DATE: 6/6/2021 TIME: 2100

VESSEL: Gunde Maersk

MASTER: _____

PILOT: M. P. Haley

CONDITIONS: Mod S'ly wind SSE'ly swell.

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- PILOT LADDER ONLY
- COMBINATION LADDER
- SIDE PORT
- OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Ladder not properly secured

- MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Vessel deeply laden. Ladder had to be moved aft of reel to accommodate combination configuration

Ladder was improperly secured to handrail. No "strongpoint on deck" available to properly secure

Signature: _____

MASTER (if available)


PILOT

