



PILOT BOARDING DEFICIENCY REPORT

DATE: 6/13/2021 TIME: 1400

VESSEL: Sealand Illinois

MASTER: _____

PILOT: M. P. Haley

CONDITIONS: Mod S'ly wind

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- PILOT LADDER ONLY
- COMBINATION LADDER
- SIDE PORT
- OTHER Trap door configuration

DEFICIENCIES (check all that apply and provide brief comment)

- GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

Ladder is aging and showed signs of wear. Not resting flat against the hull

- COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Gangway not secured to hull

- MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Signature: _____

MASTER (if available)


PILOT





