



PILOT BOARDING DEFICIENCY REPORT

DATE: 02/28/21 TIME: 1000

VESSEL: MAERSK CHICAGO

MASTER: _____

PILOT: Ryan P. Pakalik

CONDITIONS: Calm NNE Wind

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- PILOT LADDER ONLY
- COMBINATION LADDER
- SIDE PORT
- OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.) Trap door style arrangement. Ladder did not pass all of the way through the Platform

DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Incorrect trap door style combination style. The ladder did not pass all of the way through the Platform

Signature: _____

MASTER (if available)

Signature: [Handwritten Signature]
PILOT

